

# Product Safety Recall



## DeWalt Midland Gumboot

Sold at Bunnings Warehouse between 1<sup>st</sup> March 2019 and 24<sup>th</sup> July 2020

**DEFECT** Steel toe cap may be missing in some boots.

**HAZARD** If the steep cap is missing, the boots will not protect the toes from being crushed by heavy objects landing on the foot.

**WHAT TO DO** Consumers should inspect their boots to check if they have the steel toe caps. This can be done by pressing down on the ribbed toe guard at the front of each boot. If the steep cap is absent, the toe of the boot will compress. If the steel cap is missing, contact Mayo Hardware to arrange for the boots to be returned and replaced.

For further information, contact Mayo Hardware on 1300 360 211 or email [dewalt@mayohardware.com.au](mailto:dewalt@mayohardware.com.au)

**See [productsafety.gov.au](http://productsafety.gov.au) for  
Australian product recall information**